

# Maryland Inventory of Historic Properties

## Addendum


MIHP Number: QA-383

Property Name: Covington Frame House  
Property Address: Southeast side of Roe-Ingleside Road, Ingleside, MD 21644

According to interviews with long-time Ingleside residents, including Mrs. Helen Walls (who owned the building), this building was demolished in the 1960s. (SHA Architectural Historian Anne E. Bruder interview with Mrs. Helen Walls, Mrs. Ella Meredith and Mrs. Vicky Eck, 4/19/2004.)

Documentation is presented in Project Review and Compliance Files regarding MD 19 over Beaverdam Ditch, SHA Project No. QA713B21. Information provided by Anne E. Bruder, SHA, April 2004

# **Ingleside Historic District, QA-543** **Price and Goldsboro Quads** **1:24,000**



QA-383

QA-383  
Covington House  
Ingleside, Maryland  
Private

2nd quarter 19th century

The frame Covington House is a typical example of a side hall, single parlor house which has evolved into a center hall "I" house with a rear kitchen L. The most distinguishing feature of the building is the handsome stair and relatively plain but unusual architrave trim with 19th century ochre graining.

## INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

**1 NAME**

HISTORIC

AND/OR COMMON

Covington House

**2 LOCATION**

STREET &amp; NUMBER

Southeast side of Roe-Ingleside Road

CITY, TOWN

Ingleside

VICINITY OF

CONGRESSIONAL DISTRICT

1st

STATE

Maryland

COUNTY

Queen Anne's

**3 CLASSIFICATION**

## CATEGORY

☐ DISTRICT☒ BUILDING(S)☐ STRUCTURE☐ SITE☐ OBJECT

## OWNERSHIP

☐ PUBLIC☒ PRIVATE☐ BOTH

## PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED

## STATUS

☐ OCCUPIED☒ UNOCCUPIED☐ WORK IN PROGRESS

## ACCESSIBLE

☒ YES: RESTRICTED☐ YES: UNRESTRICTED☐ NO

## PRESENT USE

☐ AGRICULTURE☐ COMMERCIAL☐ EDUCATIONAL☐ ENTERTAINMENT☐ GOVERNMENT☐ INDUSTRIAL☐ MILITARY☐ MUSEUM☐ PARK☐ PRIVATE RESIDENCE☐ RELIGIOUS☐ SCIENTIFIC☐ TRANSPORTATION☒ OTHER: vacant**4 OWNER OF PROPERTY**

NAME

Joseph A. Covington

Telephone #:

STREET &amp; NUMBER

Rt. 18, Box 48

CITY, TOWN

Queenstown

VICINITY OF

STATE, zip code

Maryland 21658

**5 LOCATION OF LEGAL DESCRIPTION**COURTHOUSE,  
REGISTRY OF DEEDS, ETC.

Queen Anne's County Courthouse

Liber #: CWC 78

Folio #: 57

STREET &amp; NUMBER

Courthouse Square

CITY, TOWN

Centreville

STATE

Maryland 21617

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR  
SURVEY RECORDS

CITY, TOWN

STATE

**7 DESCRIPTION**

QA-383

**CONDITION**☐ EXCELLENT☐ GOOD☐ FAIR☒ Poor☐ DETERIORATED☐ RUINS☐ UNEXPOSED**CHECK ONE**☐ UNALTERED☒ ALTERED**CHECK ONE**☒ ORIGINAL SITE☐ MOVED

DATE \_\_\_\_\_

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Covington House is located on the south-east side of the Roe-Ingleside Road where it intersects Maryland Route 19 in Ingleside.

This 2 1/2 story frame house was constructed in three parts. The original house, probably dating to the second quarter of the 19th century, was three bays wide and one room deep, with a single flush chimney at the southwest end of a pitched gable roof. In the third quarter of the 19th century the house was extended two bays to the northeast, transforming the original side-hall, single parlor plan house into a center hall "I" house. In the late 19th century a two story rear "L" was constructed on the rear of the two bay addition.

The front facade, facing the road, is not quite symmetrical. The front door is off-set to the right of center with two 6/6 windows to the right and two more widely spaced 6/6 to the left. This pattern is repeated on the second floor with five 6/6 windows. There are three 6/6 pitched roof dormers on the third floor. A one story porch stretches across the front facade. The

CONTINUE ON SEPARATE SHEET IF NECESSARY

**8 SIGNIFICANCE**

QA-383

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The frame Covington House is a typical example of a side hall, single parlor house which has evolved into a center hall "I" house with a rear kitchen L. The most distinguishing feature of the building is the handsome stair and relatively plain but unusual architrave trim with 19th century ochre graining.

CONTINUE ON SEPARATE SHEET IF NECESSARY

**9 MAJOR BIBLIOGRAPHICAL REFERENCES**

CONTINUE ON SEPARATE SHEET IF NECESSARY

**10 GEOGRAPHICAL DATA**

ACREAGE OF NOMINATED PROPERTY \_\_\_\_\_

## VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

**11 FORM PREPARED BY**

NAME / TITLE

Orlando Ridout V, Historic Sites Surveyor

ORGANIZATION

Queen Anne's County Historical Society

DATE

5/13/80

STREET &amp; NUMBER

TELEPHONE

CITY OR TOWN

Centreville

STATE

Maryland

Field Note Book Md-1, Recorded August 9, 1979.

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
The Shaw House, 21 State Circle  
Annapolis, Maryland 21401  
(301) 267-1438

## CONTINUATION SHEET

## 7.1 DESCRIPTION

entire building has been covered with aluminum siding; the windows are fitted with aluminum storm sash. The box cornice is also modern.

The only openings on the southwest gable are a pair of four-light attic windows flanking the chimney in the upper gable. No other early detail remains visible. The rear L covers the northeast two bays of the rear facade, leaving three bays exposed. There is a door in the northeast bay with two 6/6 windows to the left, three 6/6 windows on the second floor, and three 6/6 dormers on the third floor.

The northeast gable of the main house is flush with the northeast wall of the rear wing. A modern 1/1 window has been inserted on the first floor to the left of the flush center chimney. On the second floor there is a 6/6 window to the left of the chimney and on the third floor a pair of four-light windows flank the chimney.

The rear wing is two stories high, with two rooms on each floor and assymetrical fenestration. The roof is badly deteriorated and the lower floors have suffered heavy water damage.

The interior of the main house was enlarged from



## CONTINUATION SHEET

## 7.2 DESCRIPTION

a side hall to a center hall plan. The stair rises against the northeast wall of the hall. It is an open-string stair with large turned newels, tapered round ballusters and a plain rail. A band of plain trim outlines the treads and risers. The area below the carriage is paneled with tall vertical paneling. Both parlours are heated by end chimneys. The mantels, interior trim, and doors are consistent throughout the main house, dating to the second period of construction. Yellow ochre graining has survived on the stair and some of the doors and architrave trim.

The first floor plan is repeated on the second floor but with one closet in each room and the stair hall. The woodwork is similar to the first floor trim though in some cases it is plainer. Much of the early graining has survived. The stair continues on to the third floor. It has been partitioned to conserve heat, but the banister has survived intact.

The center hall plan is repeated on the third floor. The rooms have all been finished, with plaster walls and ceilings applied to machine sawn lath secured with machine nails. The rafters are mitred and butted at the ridge; the collars are scabbed on with machine nails.


## CONTINUATION SHEET

## 7.3 DESCRIPTION

Meat House

To the rear of the house is a frame meat house 12 feet square. It has a pitched gable roof and board-and-batten siding. A wide batten door hung on wrought strap hinges is centered on the gable facing the house. The eaves are finished with a plain box cornice and plain tapered rakeboards on the gables.

The interior framing is gang-sawn, with corner posts and intermediate posts running from sill to plate. Up braces in the corners run from post to plate. The exterior siding is nailed to the sill, two horizontal intermediate rails, and the top plate. The rafters are mitred and butted at the ridge and rest on flat false plates. Gable collars are half-lapped and nailed, the remaining collars are scabbed on and nailed. The interior walls are whitewashed.





QA-383

Covington Frame House  
Ingleside, Maryland  
Orlando Ridout V 1980  
View from Northeast



QA-383

Covington Frame House  
Ingleside, Maryland  
Orlando Ridout V 1980  
View from East